



HOW TO INSTALL

RADIATION SHIELDING PLEATED TABLE SHIELD



ABOUT PHILLIPS SAFETY

Phillips Safety is the industry leader in occupational safety eyewear. In business for over 100 years, you are being served with the dedication and craftsmanship of a family owned company.

Phillips Safety has been producing occupational safety glasses since 1905 and continues to develop and produce the highest quality glasses and lenses today. A leading manufacturer of specialty safety eyewear in the United States, Phillips Safety adheres to strict ANSI Z87-2+ and EN 207 CE standard certifications, holding itself to the highest

standard and prides itself on producing glasses with the finest quality materials available.

All safety glasses produced and sold by Phillips Safety meet strict industry standards for military, medical, research laboratories, and a variety of other industries.

With Phillips Safety's dedicated team, you can rest assured knowing that all your prescription safety needs are met.

HOW TO INSTALL
RADIATION SHIELDING PLEATED TABLE SHIELD

STEPS

ATTENTION

BEFORE INSTALL THE RADIATION SHIELDING PLEATED TABLE SHIELD, YOUR IMAGING TABLE MUST BE CLEAN AND DRY.

WE RECOMMEND CLEANING YOUR IMAGING TABLE WITH CAVI WIPES.

1

WITH THE NON-SLIP PAD FACING THE IMAGING TABLE. PEEL THE PROTECTIVE FILM



HOW TO INSTALL
RADIATION SHIELDING PLEATED TABLE SHIELD

STEPS

2

**POSITION THE LEAD CURTAIN
ALIGNED WITH THE CENTER OF
YOUR TABLE.**



REMEMBER
The table surface
MUST BE completely
clean and dry.

3

**ATTACH THE ENTIRE SURFACE
WITH THE TABLE.**




4

PRESS FIRMLY TO ENSURE
ADHERANCE.




CONTACT

Should you need any further information,
please do not hesitate to contact us.

123 Lincoln Blvd, Middlesex, NJ 08845, USA 

+1 (866) 757 1307 

service@phillips-safety.com 

www.phillips-safety.com 